
Servicii de reparatie pentru auto VW Caddy

I.D.: 55407162

Data publicarii	22.03.21	Coduri CPV	50111000-6 50112100-4
-----------------	----------	------------	-----------------------

Pretul estimativ:	662,18 RON - 662,18 RON
-------------------	-------------------------

Descriere:	101/12.03.2021(RAR Bacau) inlocuit burete spatar scaun sofer
------------	--
