
Serviciul de reparatie masina de tuns gazon Stihl

I.D.: 50178950

Data publicarii	28.09.20	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Pretul estimativ: 322,04 RON - 322,04 RON

Descriere: Serviciul de reparatie masina de tuns gazon Stihl RM448 TX consta in urmatoarele proceduri:
- constatarea defectiunilor - identificarea pieselor defecte - inlocuirea pieselor defecte (filtru aer, bujie, ulei, cutit, bucsa cutit.) - testare/predare
