
Reparatie auto Dacia Duster BH 02 DSP

I.D.: 57810107

Data publicarii	09.06.21	Coduri CPV	50110000-9
-----------------	----------	------------	------------

Pretul estimativ: 1.641,45 RON - 1.641,45 RON

Descriere: reparatie auto Dacia Duster piese si manopera: ulei, filtru ulei, garnitura, lamela stergator parbriz, cartus filtrant aer, bloc filtrant, tampon soc, filtru habitaculu, filtru motorina
