

Piese de schimb

I.D.: 83197071

Data publicarii	09.06.23	Coduri CPV	34913000-0
-----------------	----------	------------	------------

Pretul estimativ: 721,09 RON - 721,09 RON

Descriere: Pompa Combustibil 7.05656.33 172021477R-1 buc,494.1200 lei Kit Reparatie Etrier Burdufuri-1 buc,18.4900 lei Suport Numar-2 buc,6.2200 lei/buc Surub Cap Hexagonal M12x140 8.8-2 buc,3.9500 lei/buc Vesta Reflex 9194 Portocalie 5B47-5 buc,9.6640 lei/buc Siguranta Fuzibila 20A 1904529907-5 buc,0.5040 lei/buc Furtun AquaFix 1/2 12.5mm-3 Ml,3.2767 lei/MI Colier Oetiker 10-16-2 buc,1.5150 lei/buc Kit Reparatie Etrier Burdufuri-4 buc,18.4875 lei/buc Surub Cap Inecat Loc.Hex. M8x45-5 buc,1.0920 lei/buc Surub Cap Inecat Loc.Hex. M8x25 10.9-5 buc,0.8400 lei/buc Email Verde Casabella 6029 0.75-3 buc,13.6133 lei/buc
