



Servicii de reparatie masina de spalat vase DIHR

I.D.: 67959479

Data publicarii 08.04.22

Coduri CPV

50800000-3

Pretul
estimativ: 454,00 RON - 454,00 RON

Descriere: Servicii de reparatie masina de spalat vase DIHR, si anume: - inlocuire - Termostat - 1 buc
