

SERVICII DE REPARARE

I.D.: 99574139

Data publicarii	01.07.24	Coduri CPV	50112100-4
-----------------	----------	------------	------------

Pretul estimativ: 6.289,77 RON - 6.289,77 RON

Descriere: SERVICII DE REPARARE MANOPERA: DEM REM ANSAMBLU CUTIE DE VITEZA 9.5H X125 LEI; SEPARARE ANSAMBLU MOTOR CUTIE DE VITEZE+REPARAT CUTIE DE VITEZA 10.1H X125 LEI; PURJARE CIRCUIT HIDRAULIC AMBREIAJ 0.9H X125 LEI; DEM REM ANSAMBLU CUTIE DE TRANSFER 3.5H X125 LEI; REGLAJ DIRECTIE 1.2H X90 LEI; DEM REM POMPA DE APA 0.7H X99.26 LEI; GOL CLAT UMLERE ANSAMBLU CIRCUIT DE LICHID DE RACIRE 0.9H X99.26 LEI; INLOCUIT CUREA DE ACCESORII 0.1H X 99.3 LEI; TEST VEHICUL 0.3H X99.27 LEI PIESE: CUREA STRIATA 1BUC X154.95 LEI; LICHID RACIRE GLACEOL RX TYPE D 1L 2BUC X48.99 LEI; BEC H7 12V/55W 1BUC X15.12 LEI; BEC 5W UF MOTRIO 1BUC X2.93 LEI; RULMENT BIELE 1BUC X93.77 LEI; PINION LIBER VIT 3 AS 1BUC X292.95 LEI; COLECTIE RONDELE CALARE PINION 1BUC X210.49 LEI; INEL SINCRON CV 2BUC X161.65 LEI; BUTUC SI BALADOR 1BUC X328.95 LEI; PINION VIT 4 AS 1BUC X310.51 LEI; RULMENT 1BUC X93.77 LEI; DEFLECTOR ULEI 1BUC X3.37 LEI; GARNITURA ETANSARE IESIRE TRANSMISIE 1BUC X114.36 LEI; GARNITURA ETANSARE ARBORE CV 1BUC X151.83 LEI; ULEI DE CUTIE DE VITEZE RENAULT 75W 1L 3BUC X144.92 LEI; SPRAY CURATATOR 1BUC X65.89 LEI; GARNITURA SILICON ADERENTA 2BUC X39.61 LEI; TOTALSERVICII: 6289.77 LEI
