

## Reparatii PERFUSOR SPACE seriile 532758 si 532755

I.D.: 70521177

Data publicarii 23.06.22 Coduri CPV 50000000-5 50422000-9

Pretul estimativ: 4.494,28 RON - 4.494,28 RON

Descriere: Reparatii PERFUSOR SPACE seriile 532758 si 532755 PERFUSOR SPACE seria 532758 COD DESCRIERE CANTITATE (buc.) PRET LEI / buc FARA TVA VALOARE LEI FARA TVA PIESE SCHIMB 34502001 LUMP SUM FOR CONSUMABLES (kit material service) 1 50.00 50.00 34521041 DRIVE PSP COMPLETE GREEN CLAWS (sistem complet de actionare seringa ) 1 1836.17 1836.17 34520945 SYRINGE HOLDER WITH PISTON BRAKE PSP (sistem prindere seringa) 1 417.26 417.26 34774386 COVER CAP CASE SP (capace suruburi echipament SP) 10 1.04 10.40 SERVICII REPARATII MANOPERA REPARATII +CALIBRARE+TSC 1 400 400 · PERFUSOR SPACE seria 532755 COD DESCRIERE CANTITATE (buc.) PRET LEI / buc FARA TVA VALOARE LEI FARA TVA PIESE SCHIMB 34502001 LUMP SUM FOR CONSUMABLES (kit material service) 1 50.00 50.00 34520970 OPERATING UNIT, COMPLETE PSP (panou operare PSP) 1 834.24 834.24 34520945 SYRINGE HOLDER WITH PISTON BRAKE PSP (sistem prindere seringa) 1 417.26 417.26 34770025 SYRINGE HOLDER FIXATION (sistem fixare panou frontal) 1 68.55 68.55 34774386 COVER CAP CASE SP (capace suruburi echipament SP) 10 1.04 10.40 SERVICII REPARATII MANOPERA REPARATII +CALIBRARE+TSC 1 400 400 TOTAL DEVIZ FARA TVA = 4494.28 LEI