
Piese de schimb+manopera_TM13SAJ

I.D.: 85811951

Data publicarii	11.08.23	Coduri CPV	34913000-0
-----------------	----------	------------	------------

Pretul estimativ: 1.748,00 RON - 1.748,00 RON

Descriere: 1. Cod SEAP: MS - Demontata/remontat parte fata BOB (extras surub rupt din ax role culisante, inlocuit 2 role, h 3, pret 208,00 Ron / h; 624,00 Ron / 3 h; 2. Cod SEAP: MS - Reparata cablaj electric, mufa panou frontal, h 1, pret 208,00 Ron / h; 3. Cod SEAP: MS - Reparata (inlocuit) protectie inox-dulap despartitor, h 1,5, pret 208,00 Ron / h; 312,00 Ron / 1,5 h; 4. Cod SEAP: MS - Reparata valize metalice, h 0,5, pret 104,00 Ron / 0,5 h; 5. Cod SEAP: E00679 - Rola BOB, buc 2, pret 250,00 Ron / buc; pret 500,00 Ron / 2 buc; TOTAL - 1.748,00 Ron / pachet
