
Inspectie service cu schimb ulei VW Crafter

I.D.: 59524554

Data publicarii	03.08.21	Coduri CPV	50112200-5
-----------------	----------	------------	------------

Pretul estimativ: 2.805,13 RON - 2.805,13 RON

Descriere: Conditii refuzate: Inspectie service cu schimb ulei (flexibil) , inlocuire filtru aer, filtru polen si filtru combustibil, service lichid frana, ventil reglaj presiune inlocuit
