

---

## Reparatie Mercedes Benz Sprinter

I.D.: 2852306

---

Data publicarii	05.06.14	Coduri CPV	50112000-3
-----------------	----------	------------	------------

---

Termenul limita pentru depunere:	09.06.14	Pretul estimativ:	12.000,00 RON
----------------------------------	----------	-------------------	---------------

---

Descriere: Reparatie:-Mercedes Benz Sprinter ,masa max.autorizata 4600 kg ,cilindree 2148,nr locuri 16 Nr.de identificare WDB9066571S179525. -actuator usa spate, -set ghidaje etrier fata +spate, -amortizoare spate + fata, -discuri frana spate, -placute frana, -senzori placute frana, -set bielete directie, -cardan.

---