
Reparat demaror autoutilitara 3.5T Ford

I.D.: 107184331

Data publicarii	19.12.24	Coduri CPV	50112100-4
Termenul limita pentru depunere:	24.12.24 13:30	Pretul estimativ:	970,00 RON - 970,00 RON
Descriere:	Reparat demaror autoutilitara 3.5T Ford, SM 43 APS, Sectia Tasnad, serviciul de reparatie va cuprinde piese+manopera: demaror, demontat- remontat electromotor.Reparatia se va executa in max 36 ore .		
