
Reparatie pompa TSURUMI, P=1,13 kW, n=3000 rpm, U=380 V
Reparatie pompa TSURUMI, P=1,13 kW, n=3000 r

I.D.: 90512568

Data publicarii	06.12.23	Coduri CPV	50511100-1
-----------------	----------	------------	------------

Pretul estimativ: 3.570,82 RON - 3.570,82 RON

Descriere: Reparatie pompa TSURUMI, P=1,13 kW, n=3000 rpm, U=380 V constand din demontare ansamblu pompa, depresare+presare stator miez pompa, rebobinare stator, revizie mecanica, reconditionare cota ermetizare, montare, ermetizare, probe pompa TSURUMI, P=1,13 kW, n=3000 rpm, U=380 V constand din demontare ansamblu pompa, depresare+presare stator miez pompa, rebobinare stator, revizie mecanica, reconditionare cota ermetizare, montare, ermetizare, probe
