

## **REPARATIE SISTEM TVCI SCOALA SURANI :**

I.D.: 52771006

---

Data publicarii	18.12.20	Coduri CPV	50610000-4
-----------------	----------	------------	------------

---

Pretul estimativ: 1.522,54 RON - 1.522,54 RON

---

Descriere: REPARATIE SISTEM TVCI SCOALA SURANI : - camera video de interior 2MP: 2 buc - camera video de exterior 2MP : 1 buc - doza legaturi : 3 buc - videobalun: 3 buc - alimentator 12V2A : 3 buc -cablu FTP : 150 mai putin

---