

Reparatie autogunoiera IF 55 ECV

I.D.: 78698636

Data publicarii 13.02.23 Coduri CPV 34913000-0 50100000-6

Pretul estimativ: 1.843,39 RON - 1.843,39 RON

Descriere: inlocuit/reparat cf deviz Sensor mounting tailgate open - suport senzor rotativ capac GPM IV Geesinknorba - 1buc; Senzor rotativ magnetic lift Geesinknorba -1 buc
