

---

## Servicii de intretinere si reparatii masini de spalat rufe

I.D.: 69083022

---

Data publicarii	12.05.22	Coduri CPV	50532000-3
-----------------	----------	------------	------------

---

Pretul estimativ: 699,55 RON - 699,55 RON

---

Descriere: Servicii de intretinere si reparatii masini de spalat rufe - Reparata masina de spalat Beko - Verificarea si probarea ansamblului, curatat filtru electrovalva, deblocat pompa evacuare, reparata placa programator cu inlocuire de piese, probe functionale. Material = 0.00 Tarif = 216.00 Total = 216.00 - Reparata masina spalata Indesit 7 kg - Verificarea ansamblului, inlocuit (demonstat-montat) rulmentii si semering, deblocat presostat, reconditionat electrovalva ,probe functionale. Material =40.32 Tarif =225.00 Total =265.32 - Reparata masina spalata Indesit - Verificarea si probarea ansamblului, demontat-montat cutie detergent, reconditionat placa programator fara inlocuire de piese, probe functionale. Material =73.23 Tarif =145.00 Total =218.23

---