
REPARATII POMPE FLYGT

I.D.: 90319831

Data publicarii	28.11.23	Coduri CPV	50511000-0
-----------------	----------	------------	------------

Pretul estimativ: 3.582,00 RON - 3.582,00 RON

Descriere: REPARATII MIXER 4,2 KW KW :rebobinat; prelucrari mecanice conexe ;echilibrarea dinamica ;
REPARATII FLYGT 4.2 KW :rebobinat ;prelucrari mecanice conexe ; echilibrare dinamica
;inlocuire rulment; REPARATII FLYGT 1.7 KW ; rebobinat ;lucrari mecanice conexe
