
Servicii de reparare masini de spalat ind. Electrolux35kg

I.D.: 79917459

Data publicarii	17.03.23	Coduri CPV	50532000-3
-----------------	----------	------------	------------

Pretul estimativ: 3.990,00 RON - 3.990,00 RON

Descriere: Reparatie masini de spalat rufe Electrolux 35kg (2 buc) ,inlocuit rezistenta electrica, inlocuit modul electronic, inlocuit sursa alimentare ,inlocuit cablaj electric protectie inverter la DGASPC SECTOR 1 / CSS. ODAI
