

Reparatie fibroscop

I.D.: 104977231

Data
publicarii

29.10.24

Coduri CPV

50422000-9

Pretul
estimativ:

15.833,00 RON - 15.833,00 RON

Descriere: eparatie fibroscop ORL 11101RP2 L DEFECTIUNI CONSTATATE Flexibil neetans; Angulare insuficienta; Camasa metalica deteriorata; Invelis camasa metalica deteriorata, cutata
