

---

## Servicii reparatie BMC

I.D.: 45991622

---

Data  
publicarii 27.04.20

Coduri CPV 50110000-9

---

Pretul  
estimativ: 6.144,54 RON - 6.144,54 RON

---

Descriere: SERVICII REPARATII BMC /PROBUS TL 48 STP, TL 53 STP inlocuit geam lateral dreapta fata b, inlocuit luneta

---