

## Cumparare materiale reparatii

I.D.: 90445296

---

|                 |          |            |            |
|-----------------|----------|------------|------------|
| Data publicarii | 29.11.23 | Coduri CPV | 44411000-4 |
|-----------------|----------|------------|------------|

---

Pretul estimativ: 3.596,05 RON - 3.596,05 RON

---

Descriere: TERMOSTAT BOILER TESY 1X54.54 CAPAC ALAMA 3/4 2X7.14 GARNITURA CL 3/4 4X0.33 DOP ZINCAT 3/4 2X3.27 SILICON SAN 1X20.92 SCORCH MARO 1X6.64 BUTELIE 330 1X25.13 BANDA AVERT. 1X58.74 CINEPA FUIOR 2X2.94 COLIER CU G 1/2 4X1.77 COT 40/45 2X1.68 COT 40/90 2X1.77 COT ALAMA 1/2 IE 2X8.32 COT C 90/18 II 4X2.77 COT C 90/18 MT 3X3.45 COT KPE 63 1X30.17 COT KPE 63 FI 1X25.13 COT Z 2 IE 6X26.81 COT Z 2 II 5X21.76 DIBLU 16X0.17 DISC 115 13X4.96 DOP ZINCAT 6/4 1X7.48 GARNITURA 2 4X2.10 HERZ AER AUT 4X36.05 HERZ ROB RETUR 1X33.53 NIPLU 20 PRESS 2X16.73 IZOLATIE 22/13 2X7.48 MUFA PR 15 4X5.80 MUFA Z 2 2X17.57 NIPLU Z 2 2X16.73 PREZON 120 11X0.67 PREZON 80 5X0.67 RACORD C 15 FE B 1X2.44 RACORD C 18 FE 2X3.78 RACORD C 18 FI 2X4.12 RACORD KPE 63 FI 1X18.40 RACORD MON 50 2X9.16 RACORD OL Z 2II 1X50.34 RADIATOR 500/1000 1X184.79 REDUCTIE Z 2-6/4 2X12.52 ROBINET SF 2 IE 3X210 SPUMA 500 2X21.77 TEAVA C 18 3X23.45 TEAVA HENCO 20 2X8.32 TEAVA Z 2 10X43.61 TUB KPE 32 4X2.94 TUB PVC 110/2M SN4 1X23.47 HERZ ROB TUR 1X37.73 DOP KPE 63 1X18.40 TUB PVC 785/1000 1X9.16 REDUCTIE S 50/40 1X5.8 HERZ ROB SF OL 1/2 2X37.73 TUB KPE 63 68X10.84 HERZ ROB SF 1/2 IE 4X29.33 COLIER C G 2 11X3.28 SPRAY 500 1X29.33

---