
Reparatie sistem supraveghere audio/video

I.D.: 44790482

Data publicarii	12.12.19	Coduri CPV	32323500-8
-----------------	----------	------------	------------

Pretul estimativ: 251,00 RON - 251,00 RON

Descriere: Inlocuire/Reparare CAMERA TURBO HD, 2 Megapixel high-performance CMOS, EXIR 2.0, 60m, Bullet, ICR, 0.003Lux/F1.2 AGC ON, Smart IR, Meniu OSD(Coaxitron), 130dB WDR, IP67, Lentila 2.8 mm; DC 12V/max. 3,4W - 1buc Set 2 bucati video balun pasiv HD 5/4/3/2 Mp - 2buc
Include manopera reparatie si reconfigurare sistem supraveghere video.
