

---

## **Servicii de reparatii instalatii racire UPS conform deviz .**

I.D.: 44651117

---

Data publicarii	18.11.19	Coduri CPV	50730000-1
-----------------	----------	------------	------------

---

Pretul estimativ: 1.945,00 RON - 1.945,00 RON

---

Descriere: Reparatii instalatii racier UPS spalat condensatoarele , filtre de purificare aer , remediat pierderi de Freon ,verificat cu spreieri detective pierderi : solutie spalat buc. 1 x 85 lei , Freon 3kg. x 190 lei=570 lei , spreii detector 2 x 45 lei , manopera reparatii = 1200 lei

---