

---

## **Servicii de reparare sistem supraveghere video si detectie incendiu**

I.D.: 49637183

---

Data publicarii	11.09.20	Coduri CPV	35120000-1
-----------------	----------	------------	------------

---

Pretul estimativ: 7.345,21 RON - 7.345,21 RON

---

Descriere: Servicii de reparare sistem supraveghere video si detectie incendiu care contine manopera si piese ( HDD 4 TB - 1 buc Cablu semnal video si alimentare - 215 ml Cablu semnal video - 176 ml Camera video dome 2 Mpx cu IR - 8 buc Camera video bullet 2 Mpx cu IR - 6 buc Video balun - 36 buc Acumulator 5Ah - 1 buc Acumulator 7Ah - 1 buc Sursa de alimentare 12V 3 Ah - 3 buc Sursa de alimentare 12V 5 Ah - 1 buc Sursa de alimentare 12V 1 Ah - 6 buc Sirena interior Iris Wsou - 1 buc Soclu sirena - 1 buc Pat cablu 25 \* 16 mm - 10 ml)

---