
Servicii de reparat aspirator Ghibli Power Extra 7P

I.D.: 75179264

Data publicarii	09.11.22	Coduri CPV	50000000-5
-----------------	----------	------------	------------

Pretul estimativ: 544,00 RON - 544,00 RON

Descriere: Servicii de reparat aspirator cu spalare Ghibli Power Extra 7P: Verificare si inlocuire pompa apa Verificare componente aspirator Desfundat circuit de apa Manopera; Transport.
