
Reparatii masina de spalat marca BEKO

I.D.: 19207704

Data publicarii	21.04.17	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Termenul limita pentru depunere:	25.04.17	Pretul estimativ:	400,00 RON
----------------------------------	----------	-------------------	------------

Descriere: Reparatii masina de spalat marca BEKO,situata in incinta C.R.R.Adaseni,com.Adaseni,jud.Botosani Masina de spalat necesita schimbarea rulmentilor de la motor,inlocuire electropompa si electrovalva,verificare si reparare,dupa caz,a placii electronice.
