

Reparatie pompa SP17-10

I.D.: 98981107

Data publicarii	17.06.24	Coduri CPV	50511000-0
-----------------	----------	------------	------------

Pretul estimativ: 11.696,18 RON - 11.696,18 RON

Descriere: Lucrari de reparatie electropompa SP17-10, care includ: includ constare, manopera si inlocuire piese, kit motor MS4000 1buc., kit reparatie inele uzura 1buc., kit ax pompa 1buc., kit rotori 2buc.
