

---

## Reparație masina de tuns gazon Husqvarna LC 153

I.D.: 75681781

---

Data publicarii	22.11.22	Coduri CPV	50531000-6
-----------------	----------	------------	------------

---

Pretul estimativ:	565,55 RON - 565,55 RON
-------------------	-------------------------

---

Descriere:	reparatie conform deviz nr. 175482 garnitura, cutit,cablu,ulei,bujie. Reparatii conform deviz nr.175478 filtru benzina, vasilina.
------------	---

---