
Servicii de reparare a automobilelor

I.D.: 73438742

Data publicarii	21.09.22	Coduri CPV	50112100-4
-----------------	----------	------------	------------

Pretul estimativ:	676,82 RON - 676,82 RON
-------------------	-------------------------

Descriere:	Reparatii Dacia Duster NT 40 BIS, schimbat schimbat saboti frina i cilindru frina spate CF.DEVIZ 9945/20.09.2022
------------	---
