
reparatie Toyota Hilux CL 03 HKV CL

I.D.: 76244158

Data publicarii	08.12.22	Coduri CPV	50110000-9 50112000-3
-----------------	----------	------------	-----------------------

Pretul estimativ: 2.336,13 RON - 2.336,13 RON

Descriere: REPARATIE AUTO TOYOTA HILUX CL 03 HKV; -INLOCUIT ULEI MOTOR SI FILTRE , INLOCUIT BUCSI BRATE INTERIOR; INLOCUIT BIELETE DIRECTIE;INLOCUIT ULEI C.V : GEOMETRIE ROTI MANOPERA = 1250 LEI (CU TVA) PIESE =1530 LEI (CU TVA) TOTAL MANOPERA SI PIESE AUTO =2780 LEI (CU TVA) PRET UNITAR 2336.13 RON
