

---

## Service sistem detectie incendiu

I.D.: 101009616

---

Data publicarii	05.08.24	Coduri CPV	31625200-5
-----------------	----------	------------	------------

---

Pretul estimativ: 348,96 RON - 348,96 RON

---

Descriere: Oferta neacceptata in termen: Service sistem detectie si avertizare la incendiu: inlocuit detector fum defect. Increase value Decrease value 348,96  Preluare informatii  Asociere la detaliu de plan  Elimina reper din achizitie

---