
Servicii de reparatie uscator de rufe - HEINNER

I.D.: 69107433

Data publicarii	13.05.22	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Pretul estimativ:	563,95 RON - 563,95 RON
-------------------	-------------------------

Descriere:	Servicii de reparatie uscator de rufe - HEINNER - inlocuire -carlig usa - 1 buc, curea - 1 buc
------------	--
