
Revizie tehnica SV 04 SKY, inlocuit filtre, ulei, buson

I.D.: 35222770

Data publicarii	11.04.19	Coduri CPV	50112200-5 50100000-6
-----------------	----------	------------	-----------------------

Pretul estimativ:	1.358,10 RON - 1.358,10 RON
-------------------	-----------------------------

Descriere: Servicii de reparare si intretinere autovehicul VW CRAFTER ce includ:inlocuire ulei motor,buson baie ulei,filtru ulei,filtru polen,filtru aer,filtru carburant,verificat comanda turbo si vacuum,tensionare arcuri lamelare.
