

Prestari servicii

I.D.: 44979134

Data publicarii	20.03.20	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Pretul estimativ: 2.268,90 RON - 2.268,90 RON

Descriere: Spalatorie: reparat uscator de rufe Imesa: - sudat bucsa la volanta - 168.06 lei Spalatorie: - reparat masina de spalat Imesa HS 4022: - demontat / montat , schimbat rulmenti, semering - 2100.84 le
