
Kit reparatie pompa WILO EMU FA 25.93D + T 30-6/48K (serie 650153217)

I.D.: 57451642

Data publicarii	27.05.21	Coduri CPV	42124290-3
-----------------	----------	------------	------------

Pretul estimativ: 35.166,35 RON - 35.166,35 RON

Descriere: 1.Kit reparatie pompa WILO EMU FA 25.93D + T 30-6/48K (serie 650153217) Incluzand : setul de etansari mecanice, rulmenti, garnituri, ulei camera etansare, inel de uzura mobil, inel de uzura fix, etc. 2. Kit reparatie pompa SULZER XFP201G-CB2.3-PE110/6-G-50Ex (serie 0009643) Incluzand : setul de etansari mecanice, rulmenti, garnituri, ulei camera etansare, etc
