

Motoare chirurgicale Drill si atasamente

I.D.: 98003467

Data publicarii	27.05.24	Coduri CPV	50000000-5
-----------------	----------	------------	------------

Pretul estimativ: 39.222,00 RON - 39.222,00 RON

Descriere: PIESE DE SCHIMB PENTRU MOTOR GA672 (SN: 3461) - 1 BUC - 3838.00 b. SERVICII REP410-RE002 REPARATIE COMPLETA AESCULAP TECHNICAL SERVICE - 1 BUC KIT PIESE DE SCHIMB PENTRU MOTOR GA672 (SN: 3457) - 1 BUC - 5065.00 b. SERVICII REP410-RE002 REPARATIE COMPLETA AESCULAP TECHNICAL SERVICE - 1 BUC KIT PIESE DE SCHIMB PENTRU MOTOR GA672 (SN: 3459) - 1 BUC - 5065.00 b. SERVICII REP410-RE002 REPARATIE COMPLETA AESCULAP TECHNICAL SERVICE - 1 BUC KIT PIESE DE SCHIMB PENTRU MOTOR GA672 (SN: 3458) - 1 BUC - 5745.00 b. SERVICII REP410-RE002 REPARATIE COMPLETA AESCULAP TECHNICAL SERVICE - 1 BUC KIT PIESE DE SCHIMB PENTRU ATASAMENT BROSE GB643R (SN: 2640) - 1 BUC - 4521.00 b. SERVICII REP410-RE002 REPARATIE COMPLETA AESCULAP TECHNICAL SERVICE - 1 BUC KIT PIESE DE SCHIMB PENTRU ATASAMENT BROSE GB643R (SN: 2655) - 1 BUC - 7509.00 b. SERVICII REP410-RE002 REPARATIE COMPLETA AESCULAP TECHNICAL SERVICE - 1 BUC KIT PIESE DE SCHIMB PENTRU ATASAMENT BROSE GB643R (SN: 2648) - 1 BUC - 4503.00 b. SERVICII REP410-RE002 REPARATIE COMPLETA AESCULAP TECHNICAL SERVICE - 1 BUC KIT PIESE DE SCHIMB PENTRU MOTOR GA675 - 4 BUC - 744.00 b. SERVICII REP410-RE002 REPARATIE COMPLETA AESCULAP TECHNICAL SERVICE - 1 BUC
