

Materiale constructii - reparatii curente

I.D.: 91162675

Data publicarii	21.12.23	Coduri CPV	44190000-8
-----------------	----------	------------	------------

Pretul estimativ: 26.075,48 RON - 26.075,48 RON

Descriere: izoflor 5mm 1.2*0.5m=83.8mp*5.4622, izoflor 5mm=24*5.0420, izoflor 6mm=304mp*5.4622, parchet 10mm ac5 1.727mp/pach=281,501mp*54.6218, banda mascare 50*45=5buc*10.084, colt exterior =24*2.0168, colt int=34buc*2.0168, element imbinare =28buc*2.0168, terminatie smart =5buc*2.0168, plinta smart =41buc*13.4454, silicon sanitar alb =6*16.8067, surub cu diblu 6*60=400buc*0.1429, panza fierastrau vertical =1*10.5042, banda mascare 38*40=6buc*4.6218, conector lm 55 stejar =13buc*1.6807, terminatie dr 67 stejar luminos =4buc*1.6807, terminatie dr 16 stejar=4*1.6807, usa lemn stejar inchis 10-88=5buc*672.2689, colt exterior 55 stejar =13*1.6807, plinta 67 stejar =20buc*12.6050, colt interior 67 stejar =13*1.6807, bca 600*100*250=0.45*445.3782, surub montaj ferestre 7.5*112=30buc*0.6723, spuma polit so 750=3buc*25.2101, surub montaj ferestre 7.5*150=13buc*0.6723, glet ceresit ct 126,20kg=8saci*34.4538, profil pv cu plasa 2.5m=20buc*4.2017, panza abraziva 120=15ml*2.5210, inenvaiss lavabila 15l=1*96.6387, tablou 24 module =1*60.5042, sina cu 1m=2*8.4034, bara siguranta 2p 63a =1buc*62.1849, sina siguranta =3buc*8.0672, tablou metalic 40*30*20=1*262.1849, diferential 16a =9buc*159.6639, siguranta autom 1p+n10a=9buc*30.2521, diferential 4p 63a abb=1*252.1008, bara siguranta 1P+n63a=1buc*62.1849, cablu 6=40ml*4.2017, tasta falsa 20056=4*2.9412, priza internet gewis =4buc*42.0168, rama 6pgewiss =4buc*13.8655, priza 2p gewis =8buc*12.605, suport 6p gewis =4buc*8.4034
