

## **Serviciul de reparatie Spalator de pardoseli Karcher**

I.D.: 40896509

---

Data publicarii	20.12.19	Coduri CPV	50800000-3
-----------------	----------	------------	------------

---

Pretul estimativ: 2.101,66 RON - 2.101,66 RON

---

Descriere: Serviciul de reparatie spalator de pardoseli Karcher: - constatarea defectiunilor - identificarea pieselor defecte - inlocuirea pieselor defecte (regulator deplasare, tahograf, perie cilindrica, turbina aspiratie, etc...) - testare/predare

---