

SERVICII REPARATIE MOTOR MERCEDES SPRINTER

I.D.: 97693098

Data publicarii	22.05.24	Coduri CPV	50110000-9
-----------------	----------	------------	------------

Pretul estimativ: 9.884,85 RON - 9.884,85 RON

Descriere: GARNITURA GALERIE ADMISIE-70.59 ELEMENT INJECTOR-20.17 TERMOSTAT LICHID RACIRE-91.60 FURTUN COMBUSTIBIL-133.61 ELEMENT STECHER PRIZA INJECTOR-10.92 FILTRU AER BOSCH-54.62 FILTRU ULEI BOSCH-24.37 GARNITURA CHIULOASA-169.75 SET GARNITURI CAPAC SUPAPE-94.64 GARNITURA GALERIE EV-33.61 GARNITURA EV F-31.09 MATERIALE MICI CONSUM-95.80 KIT DISTRIBUTIE-644.54 POMPA ULEI-391.60 LANT POMPA ULEI-79.83 POMPA APA-357.98 SET SURUB CHIULOASA-57.14 GARNITURA GALERIE EVACUARE-15.97 RADIATOR ULEI-180.67 SIMERING AX CAME-31.09 GARNITURA CAPAC DISTRIBUTIE-11.77 GARNITURA RADIATOR ULEI-10.08 GARNITURA POMPA ULEI-47.90 SEGMENTI PISTON-332.77 GARNITURA TURBO-15.13 GARNITURA FILTRU ULEI-5.88 CUZINETI ARBORE-295.80 CUZINETI BIELA-424.37 SIMERING AX-88.24 INEL ETANSARE-3.36 SILICON VICTOR REINZ-29.41 MANOPERA RECONDITIONARE CHIULOASA-714.29 BUJIE INCANDESCENTA SET-151.26 PATINA LANT DISTRIBUTIE-40.34 COLIER FURTUN-6.72 FURTUN CAUCIUC SISTEM RACIRE-82.35 COLIER FURTUN-13.45 FILTRU COMBUSTIBIL-131.09 GARNITURA EVAC-26.09 ANTIGEL-63.02 APA DISTILATA-10.08 ULEI TRANSMISIE-70.59 ULEI MOTOR-369.74 GARN TEAVA EVACUARE RETUR SCURGERE ULEI -15.13 TEAVA ALIMENTARE TURBO-257.98 MANOPERA INCARCARE FREON 126.05 MANOPERA REPARATIE MOTOR-3949.58
