
Reparat auto LANDROVER

I.D.: 50696795

Data publicarii	15.10.20	Coduri CPV	50110000-9
-----------------	----------	------------	------------

Pretul estimativ: 4.004,20 RON - 4.004,20 RON

Descriere: Bieleta antiruliu 67.23 Motorina 42.01 Rulment presiune ambreaj 462.18 Ulei transmisie 50.42 Pivot inf.stg.79.84 Pivot inf.dr. 79.84 Set ambreaj 663.86 Ulei diferential 33.62 Pompa centrala ambreaj 462.18 Senzor ABS 168.06 Lichid frana 25.21 Cilindru frana 75.63 Niplu frana 25.21 Conducta frana 21.01 Set rulment roata 386.56 Senzor ABS 109.24 Cauciuc pedala 25.21 Inl.set ambreaj si rulment presiune 378.15 Inlocuit pivot inferior stg/dr. 84.04 Inlocuit pompa ambreaj 134.46 Inlocuit stabilizator fata dr. 42.01 Inlocuit ulei in C/V si in diferential fata 84.04 Curatat auto int/ext. 50.42 Inlocuit set rulment roata spate dr.100.84 Inlocuit senzor ABS spate dr.117.64 Inlocuit set rulment roata fata stg. 126.05 Inlocuit senzor ABS fata stg. 67.23 Reparat frana spate 42.01
