

Pachet reparatie motopompa HONDA WT20X

I.D.: 98326258

Data publicarii 04.06.24 Coduri CPV 44423000-1 50800000-3

Pretul estimativ: 189,58 RON - 189,58 RON

Descriere: BUJIE BS -OHV 992304 1 Curatat carburator in baie de ultrasunete 1 SPRAY CURATITOR
FRANE 0,4 Ulei STIHL 10 W 30 - 55L 0,6 Opritor 1 Manopera reparatie utilaje 1 0,8
