
Reparatie pompa ape uzate Wilo EMU FA08.52W+FK17.1-4/8K (serie 650178684)

I.D.: 91128718

Data publicarii	18.12.23	Coduri CPV	50510000-3
-----------------	----------	------------	------------

Pretul estimativ: 14.127,30 RON - 14.127,30 RON

Descriere: Reparatie pompa ape uzate Wilo EMU FA08.52W+FK17.1-4/8K (serie 650178684), constand din: - schimbare kit reparatie R2; - schimbare turbina fonta fi170 mm; - manopera aferenta.
