

Reparatie buldoexcavator

I.D.: 41685573

Data
publicarii 15.01.19

Coduri CPV 34913000-0 44523300-5 50000000-5

Pretul
estimativ: 2.400,00 RON - 2.400,00 RON

Descriere: alternator 1bc semeringuri etansare 2 bc inlocuit semeringuri buldoexcavator, curatat radiatoare, confectionat bucxse protectie semering, 10 ore demontat si inlocuit alternator buldoexcavator 4 ore
