

---

## **Constatare defectiuni si inlocuire sistem UPS si configurare APC Smart UPS 1500VA LCD RM 2U**

I.D.: 76995902

---

Data publicarii	29.12.22	Coduri CPV	50116100-2
-----------------	----------	------------	------------

---

Pretul estimativ: 25.210,10 RON - 25.210,10 RON

---

Descriere: Constatare defectiuni/inlocuire sistem UPS 5 x 1000 RON Instalare si configurare APC Smart 5 X 1552.02 RON UPS 1500VA LCD RM 2U 230V cu Smart Connect 5 x 2490 RON Servicii deductibile in baza legii 448/2006

---