
Servicii reparatii masina spalata automata

I.D.: 43034486

Data publicarii	31.07.19	Coduri CPV	50532000-3
-----------------	----------	------------	------------

Pretul estimativ: 247,88 RON - 247,88 RON

Descriere: Servicii reparatii masina spalata automata Electrolux Verificarea produsului ,reparat tambur in bazin (decapsat,capsat,inlocuit rulmenti si semering,capsat si siliconat) reconditionat balama hublou,probe functionale Material = 111,77 (fara tva) Tarif = 136,11 (fara tva) Total = 247,88
