

---

## **Servicii Reparatie BH13TAT**

I.D.: 51140519

---

Data publicarii	30.10.20	Coduri CPV	50110000-9
-----------------	----------	------------	------------

---

Pretul estimativ: 790,77 RON - 790,77 RON

---

Descriere: Reparatii Service manopera 216 ron ( demontat/ montat piese de schimb,inspectie service schimb ulei, diagnoza, inlocuit piese ) piese schimb 574.77 ( surub, inel, filtru ulei/aer/ polen, ulei Castrol mat. mici)

---