
Servicii intretinere imprimante birou

I.D.: 104717998

Data publicarii	23.10.24	Coduri CPV	50000000-5
-----------------	----------	------------	------------

Pretul estimativ:	630,00 RON - 630,00 RON
-------------------	-------------------------

Descriere:	Reparatie imprimanta Lexmark MX510 ds - Inlocuire Fuser unit (Unitate cuptor)
------------	---
