
Servicii de reparare autoturism Dacia Duster MAI 42596

I.D.: 55172023

Data publicarii	15.03.21	Coduri CPV	50112100-4
-----------------	----------	------------	------------

Pretul estimativ: 782,14 RON - 782,14 RON

Descriere: Servicii de reparare autoturism Dacia Duster MAI 42596 - diagnosticare KTS, verificare instalatie electrica , inlocuire bujii. Oferta cuprinde consumabilele (bujii) si manopera aferenta.
