
Reparat microbuz MERCEDES SPRINTER

I.D.: 97053482

Data publicarii	09.05.24	Coduri CPV	34300000-0 50110000-9
-----------------	----------	------------	-----------------------

Pretul estimativ:	2.025,00 RON - 2.025,00 RON
-------------------	-----------------------------

Descriere:	Reparat microbuz Mercedes Sprinter - electrice, inlocuit comutator coloana directie, inlocuit panou de sigurante
------------	--
