
Serviciu de reparatie cuptor Lainox si marmita Ozti

I.D.: 73510761

Data publicarii	27.09.22	Coduri CPV	71356000-8
-----------------	----------	------------	------------

Pretul estimativ: 1.638,00 RON - 1.638,00 RON

Descriere: Oferta refuzata: Serviciu de reparatie cuptor Lainox si marmita Ozti DESCRIERE: Cuptor Lainox REB104M Termostat de lucru 1 260lei, Marmita Ozti Valva de apa 2 cai 1* 158 lei, Valva de apa 1 cale 1* 180 lei, Regulator energie 1* 140 lei, Manopera totala constatare si reparatie 1* 750 lei, Deplasare tehnicieni 2 *75 lei
