

Interventie service BC 3000 +

I.D.: 53912377

Data publicarii	03.02.21	Coduri CPV	50421000-2
-----------------	----------	------------	------------

Pretul estimativ: 2.031,00 RON - 2.031,00 RON

Descriere: Interventia include inlocuirea urmatoarelor piese: - Seringa 50 µL: 1 buc. X 1.587,00 LEI - Filtru de aer: 4 buc X 111,00LEI/buc Manopera service x 3 ore (gratuit conform contract service) Transport service (gratuit conform contract service) PREZENTA TINE LOC DE COMANDA
